a complete engineering & construction management company



154 Business Centre Drive • Miramar Beach, Florida 32550 • Phone: 850.837.7454 • ECM-engr.com

September 30, 2024

Majestic Beach Resort Towers I & II HOA 10901 Front Beach Road Panama City Beach, FL 32407

- ATTN: Mr. Paul Shamblin, CAM Association Manager
- Re: Milestone Inspections Certifications Majestic Beach Resort Towers I & II Amenities Building and Parking Garage Structure Panama City Beach; Bay County, FL

Dear Mr. Shamblin:

As requested, *ECM* performed the required Milestones Phase I visual inspections to observe, document, and assess the existing condition of the condominiums buildings referenced above. The focus of the Milestone Phase I report is to observe the existing conditions related to structural components of the building and assess the level of safeness. The intent of the study, as outlined in Florida Statute 553.899, is to provide a condition assessment focusing on critical structural elements related to load bearing and/or load transfer capabilities to building structure. This Milestone inspection is to identify substantial structural deterioration only, not to address building code, fire code, environmental or regulatory compliance issues. This Phase I report is based on deficiencies found during our walk through inspection of the exterior and common habitable areas. The visual inspection is of readily accessible areas as well as information provided by the association. A Phase I Milestone does not include any destructive investigation. Please refer to attached Phase I report.

ECM also performed the required inspections during the construction activities associated with the recommended repairs outlined in the Milestone Phase I report. The purpose of a Phase II Milestone Inspection in Florida is to confirm the structural integrity of a building and recommended repairs to any damaged areas noted in the Condition Survey Assessment Report were properly completed and the building's Structural Integrities have been restored and safe for use.

The attached Milestone Inspections Phase I and Phase II forms were filled out and certified as required. Please accept this letter to further confirm that after reviewing the property, it is our professional engineering and construction opinions that all deficiency items listed in Milestone Phase I Inspection Report were addressed and properly repaired/restored. Therefore, **Majestic Beach Resort Association has PASSED the Milestone Inspections Phase II**.

Milestone Inspections Certifications Majestic Beach Resort Towers I & II Amenities Building and Parking Garage Structure Panama City Beach; Bay County, FL

Page 2 of 2

Thank you for the opportunity to be of service to the Majestic Beach Resort Condominiums Owners Association.

Sincerely,

(FBPR CA8419)

John H. Elamad



John H. Elamad, MS, PE, SI, CGC President

Florida Registration #68840 Special Inspector # 6984312 Florida Certified Gen. Contractor #1505051 Int'l Code Congress Building Inspector #5133268

cc: Mr. Mark McWaters Panama City Beach Building Official

Senior Member



FORM EB 18-2024 MILESTONE INSPECTION REPORT FORM

PHASE 1 - Milestone Inspection

0	
Inspection Firm or Individual E C M, John H. Elamad, PE Name:	
Address: 154 Business Centre Dr., Miramar Beach, FL 32550	
Telephone 850-837-7454 Number:	
Inspection Commenced 10/29/2021 Date:	Inspection Completed Date: 11/28/2022
No Repairs Required Repairs are required	red as outlined herein.
Phase 2 inspection is required	
Phase 2 inspection is required, and the need is of such a	a critical nature that it is time sensitive
Licensed Design Professional:	Architect
John H. Elamad, MS, PE, SI, CGC, DFE	No. 68840
License 68840 Number:	NO. 68840 * STATE OF * STATE OF * FLORIDA
I am qualified to practice in the discipline in which I am here Signature:	by signing, Date: $\frac{9/12/2024}{2024}$

This report has been based upon the minimum inspection guidelines for building safety inspection as listed in *Chapter 18 of the Florida Building Code, Existing Building.* To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

1. DESCRIPTION OF STRUCTURE				
a.	Name on Title: Majestic Beach Tower I and II, Amenity Building, and Parking Structure			
b.	Street Address: 10901 and 10811 Front Beach Rd., Panama City Beach, FL 32407			
c.	Legal Description: Tower I, Amenity, and Parking - 34881-575-000; Tower II - 34881-577-000			
d.	Owner's Name: Majestic Beach Resort Community Association, Inc.			

e.	Owner's Mailing Address:	
	495 Richard Jackson Blvd., Panama City Beach, FL 3240	
f.	Email Address: pshamblin@rcamflorida.com	Contact Number: 850-563-1015
g.	Folio Number of Property on which building is located:	
h.	Building Code Occupancy Classification: Multi Family Dwelliing/Condominium	
i.	Present Use: Multi Family Dwelling/Condominium	
j.	General Description: 2 - 23 Story Condominiums	Type of Construction: Concrete Rigid Frame
k.	Square Footage:	
	1. Total building area: 828,288	Number of Stories: Building 1 & 2 - 23 Stories Parking-6 Stories; Amenities:2 Story
	2. Building footprint area: 97,902	
١.	Name of the Condo or Coop entity:	
m.	Special Features: Majestic Beach Tower I Condominium; Majestic Beach Tower II, Co	ondominium; and Pedestrian Bridge Connecting
	Parking Structure to Condominiums Buildings	
n.	Describe any additions to original structure:	
	Not Applicable	
о.	Distance to the coast:	
	Directly on the Beach Front	



2. PRESENT CONDITION OF STRUCTURE					
a. General A	lignment (Note: G	ood, Fire, Poor,	Explain if significa	nt):	
1. Bulging:		Good	Fair	Poor	Significant (Explain):
2. Settleme	nt:	Good	Fair	Poor	Significant (Explain):
[
3. Deflectio	ns:	Good	Fair	Poor	Significant (Explain):
4. Expansio	n:	Good	Fair	Poor	Significant (Explain):
L					
5. Contract	ion:	Good	Fair	Poor	Significant (Explain):
b. Portion Sh	owing Distress (N	ote: Beams, Colu	umns, Structural W	/alls, Floor, Roofs,	Other):
Refer to Engineering Report dated 4/28/2022					
	2				
	onditions – Descrik penetration and st		tions of finishes, n	oting cracking, spa	Illing, peeling, signs of
Refer to 1	Engineering Rep	ort			
	- 3				

d.	Cracks – Note location in significant members. Identify crack size as HAIRLINE if barely discernible; FINE if less than 1mm in width; MEDIUM if between 1mm and 2mm in width; WIDE if over 2mm:
e.	General extent of deterioration – Cracking or spalling concrete or masonry, oxidation of metals; rot or borer attack in wood:
f.	Note previous patching or repairs: Not Applicable
g.	Nature of present loading indicate residential, commercial, other estimate magnitude: Multi Family Resident Dwelling and Hotel
3 INS	PECTIONS
a.	Date of notice of required inspection: 7/9/2021
b.	Date(s) of actual inspection: 10/29/2021 thru 11/28/2021 and 3/29/2024 (Bridge)
C.	Name and qualifications of the individual preparing report: Professional Engineer, Special Inspector, Certified General Contractor and Building Inspector
d.	Description of laboratory or other formal testing, if required, rather than manual or visual procedures:
	Not Applicable
	Page 4 of 21

e. S	ructural Repairs – note appropriate line:
1	None required
2.	Required (describe and indicate acceptance) Refer to Engineering Report
f. u	as the property record been researched for any current code violations or Yes Yes No
Explanati	on/Comments:

4. SU	PPORTING DATA ATTACHED
a.	Sheets of written data: Report 4/28/2022 and Bridge Report 4/28/2022
b.	Photographs: Refer to Report
c.	Drawings or sketches: Not Applicable
d.	Test reports:Not Applicable

5. FOUNDATION

a.	Describe building foundation:
	Deep Piles and Concrete Pile Caps Foundation

b. Is wood in contact or near soil? (Yes/No): <u>NO</u>

c. Signs of differential settlement? (Yes/No) <u>NO</u>

d. Describe any cracks or separation in the walls, column or beams that signal differential settlement: <u>Not Applicable</u>

e.	Is there additional sub-soil Yes Yes No
1.	If yes, explain:
fley	water drained away from foundation? (Yes/No): Yes
g. Is ti	here additional sub-soil investigation required? (Yes/No): <u>No</u> 1. Describe:

6. MASONRY BEARING WALL – Indicate good, fair or poor on appropriate lines				
a. Concrete masonry units:	Good Fair Poor			
b. Clay tile or cotta units:	Good Fair Poor			
c. Reinforced concrete tie columns:	Good Fair Poor			
d. Reinforced concrete tie beams:	Good Fair Poor			
e. Lintel:	Good Fair Poor			
f. Other type bond beams:	Good Fair Poor			
g. Masonry Finishes – Exterior :				
1. Stucco:	Good Fair Poor			
2. Veneer:	Good Fair Poor			
3. Paint Only:	Good Fair Poor			
4. Other:	Good Fair Poor			
4a. Explain:				
,				
	Page 6 of 21			

Not applicable		
i.	Spalling – In beams, columns, or others, including locations (description):	
	Refer to Engineering Report	
	Rebar corrosion – Check appropriate line:	
j.	 None Visible Minor – Patching will suffice Significant – Patching will suffice Significant – Structural repairs required 4a. Describe: 	
k.	Were samples chipped out for examination in spalled areas?	
	 No Yes - Describe color, texture, aggregate, general quality: 	

7. Fl	OOR AND ROO	DF SYSTEM	
a.	Roof:		

1) Roof pitch Flat Pitched
2) Roof structural framing Wood Steel Concrete
3) Structural framing
condition Good Fair Poor
 A) Roof deck material Concrete Wood Structural concrete on steel deck
5) Roof cladding type ☐ Tile ✓ Single ply (Membrane) ☐ Asphalt shingles _ Metal ☐ Built-up roofing (BUR) Other
6) Roof covering condition Condition Good Fair Poor

Page 8	of 21
l'ugo o	01 21



7)	Note water tanks, cooling towers, air conditioning equipment, signs, other heavy equipment and condition of support: Not Applicable			
8)	Note types of drains, scuppers, and condition: Not Applicable			
9)	Describe parapet construction and current condition:			
	Not Applicable			
2				
10)	Describe mansard construction and current condition: Condition Good Fair Poor			
	Not Applicable			
11)	Describe any roofing framing member with obvious overloading, overstress, deterioration, or excessive deflection: Not Applicable			

12) Note any expansion joint and condition: Condition	Good	Fair	Poor

b. Floor System(s):	
 Describe (Type of system framing, material, spans, condition, balconies): Condition Good Fair Structural Post Tension Concrete slab at buildings. Pre-Cast Concrete Double Tees at Garage 	Poor
 Balcony structural system Edge and building face supported Cantilever 	
 Balcony exposure (if structure is on the coast) Ocean facing 	
Non-ocean facing	
 Balcony construction Concrete Steel framing with concrete topping Wood Other (define in narrative) 	
	Page 10 of 21

5. Balcony condition rating
Good -
Fair (e.g., minor cracking, minor rebar corrosion – patching will suffice)
Poor (e.g., significant cracking, rebar corrosion requiring repairs)
N/A
6. Balcony condition description (e.g., spalling, cracking, rebar corrosion)
Minor Balcony edge spalling in very few balconies
7. Stairs and escalators – Indicate location, framing system, material, and condition:
Reinforced Cast in Place Concrete
2 Damps Indicate location framing protons material and applition.
8. Ramps – Indicate location, framing system, material, and condition:
Not Applicable
9. Guardrails – Indicate type, location, material, and condition:
Guard system
Wood Stainless Glass
Aluminum Concrete Kneewall Other
Good Condition

 10. Guard condition (define ratings depending on guard system) Good
Fair Poor
c. Inspection – Note exposed areas available for inspection, and where it was found necessary to open ceilings, etc. for inspection of typical framing members:
Inspected all Buildings and Parking Garage structure exposed areas. This included floor structures, railing, stairs, elevator
shafts, columns, beams and walls. Not necessary to perform any intrusive destructive measures of inspection.
Please refer to the Engineering Report attached.

8. STE	EL FRAMING SYSTEM
a.	Full description of system: Painted Structural Steel Pedestrian Bridge connecting 2nd Floor of Building to Parking Garage Structure. Please refer to Engineering Report
b.	Exposed Steel – Describe condition of paint and degree of corrosion:
	Some Corrosion was noted on exposed structural steel member
с.	Steel Connections – Describe type and condition:
	Some Corrosion was noted on exposed structural plates, bolts, and connections. Condition is Fair.

d.	Concrete or other fireproofing – Describe any cracking or spalling and note where any covering was removed for inspection:
	Not Applicable
e.	Identify any steel framing member with obvious overloading, overstress, deterioration or excessive deflection (provide location(s)):
	Not Applicable
f.	Elevator sheave beams, connections, and machine floor beams – Note column:
	Good Condition
9. CON	ICRETE FRAMING SYSTEM
a.	Full description of structural system:
	Piles, Pile Caps, Reinforced Post Tension Slabs, Columns, Beams, and Shear Walls

1.	Significant	



Significant

Description of members affected, location and type of cracking:

Not Applicable

c. General condition:

GOOD

d.	Rebar	Corrosion – Check appropriate line:
	1.	None Visible
	2.	Location and description of members affected and type
	3.	✓ cracking Significant – Patching will suffice
	4.	Significant – Structural repairs required (Describe):
	4.	Significant – Structural repairs required (Describe).
20-5-7927975-79753		in Parking Garage Structure from Traffic wear and tear and missing bearing pad. In buildings, balcony slab g occurred exposing a few corroded rebars. Please Refer to Report
euge	es spanni	
e.	Were	samples chipped out for examination in spalled areas?
	1.	No
	2.	Yes – Describe color, texture, aggregate, general quality:
f.		fy any concrete framing member (e.g., slabs and transfer elements) with obvious overloading, ress, deterioration (e.g., efflorescence at underside of slab or at base of column or wall) or
		sive deflection (provide location(s)):
	NONE	
	-	
10 W		S, STOREFRONTS, CURTAINWALLS AND EXTERIOR DOORS
10. W		3, STOREPRONTS, CORTAINWALLS AND EXTERIOR DOORS
a		Ictural Glazing on the exterior envelope of Yes No
	thre	eshold building:
		revious Inspection Unknown
L	U	ate:
	2. D	escription of Curtainwall Structural Glazing and adhesive sealant:
	-	Good Condition
	3. D	escribe condition of system:
		GOOD
	_	3000
	_	Page 14 of 21
		· · · · · · · · · · · · · · · · · · ·



г

1.	Type (wood, steel, aluminum, sliding glass door, other):
	Unknown
2.	Anchorage type and condition of fasteners and latches:
3.	Sealant type and condition of sealant:
4.	General Condition:
	Good
5.	Describe repairs needed:
NOC	DD FRAMING

Not Applicable

b. Indicate condition of the following:

1. Walls: Not Applicable

Page 15 of 21

2. Floors: Not Applicable Roof member, roof trusses: _____ Not Applicable c. Note metal fitting (i.e., angles, plates, bolts, splint pintles, other and note condition): GOOD d. Joints - Note if well fitted and still closed: Well Fitted and Closed e. Drainage – Note accumulations of moisture: None Ventilation – Note any concealed spaces not ventilated: Not Applicable

g.	Note any concealed spaces opened for inspection:
	None
	2 m / ·
h.	Identify any wood framing member with obvious overloading, overstress, deterioration, or excessive deflection:
	None
12. BU	ILDING FAÇADE INSPECTION
a.	Identify and describe the exterior walls and appurtenances on all sides of the building (cladding type, corbels, precast appliques, etc.):

Stucco

b. Identify attachment type of each appurtenance type (mechanically attached or adhered): ______

Adhered

c. Indicate the condition of each appurtenance (distress, settlement, splitting, bulging, cracking, loosening of metal anchors and supports, water entry, movement of lintel or shelf angles or other defects):

Good. No Problems Noted.

13. SPECIAL OR UNUSUAL FEATURES IN THE BUILDING

a. Identify and describe any special or unusual features (i.e., cable suspended structures, tensile fabric roof, large sculptures, chimney, porte-cochere, retaining walls, seawalls, etc.):

None

Page 17 of 21



b. Indicate condition of special feature, its supports and connections: ______

Not Applicable

14. DETERIORATION

a. Based on the scope of the inspection, describe any structural deterioration and describe the extent of such deterioration.

.

Minor Corrosion of steel elements and connections. Minor Balcony slab edges spalling. Minor exposed rebars rusted.

PHASE 2 Milestone Inspection

1. DESCRIPTION OF STRUCTURE	
a. Name on Title: Majestic Beach Tower I and II, Amenity Building, and Parkir	ng Structure
b. Street Address: 10901 Front Beach Road, Panama City Beach, FL 32407	
c. Legal Description: 34881-575-000 and 34881-577-000	
d. Owner's Name: Majestic Beach Resort Community Association, Inc.	
Name of the Condo or Coop entity along with contact information:	
Name: Majestic Beach Resort Community Association, Inc.	
Address: 495 Richard Jackson Blvd.; Panama City Beach, FL 32407	
Telephone Number: 850-563-1015	
• Name and contact information of the licensed individual(s) conducting the i	nspection
Inspection Firm or Individual E C M, John H. Elamad, MS, PE, SI	
Address: 154 Business Centre Dr., Miramar Beach, FL 32550	
Telephone 850-837-7454 Number:	
Inspection Commenced Total Commenced Total Composition	08/29/2024 leted Date:
 Provision for signature and seal of the licensed individual conducting the inst 	spection
Licensed Design Professional: Engineer Architect	No. 68840
Name:	* * * STATE OF PORIDA
	CORIDA
\bigcirc	Seal

Signature: X 5 4

n which I am hereby signing, Date: <u>9/12/2024</u>

1. Describe references cited under Phase 1 report for follow up:

Please refer to Engineering Report of Buildings, Parking Garage Structure, and Pedestrian

2. Identify the damage and describe the extent of the repairs needed along with repair recommendations:

Please refer to the Engineering Report of Buildings, Parking Garage Structure and Pedestrian Bridge

3. Identify and describe areas requiring added inspection as well as results of any testing:

Required Re-Inspection of areas noted above and Engineering Reports

4. Describe manner and type of inspections performed: Visual thorough inspection of each item listed in the Engineering Report

> <u>Note:</u> When testing and at the discretion of the design professional, scientific testing protocols must be used in addition to visual inspection techniques for determining the structural integrity of a building.

5. Provide graded urgency of each recommended repair



Not Urgent but recommended Repairs to be completed by the end of 2024.

6. State whether unsafe or dangerous conditions exist, as these terms are defined in the Florida Building Code, were observed.

NONE

7. Identify and describe any items requiring additional inspections

Same items identified in Engineer's Report and items in 1 and 2 above