## DBPR HR-7020 - Division of Hotels and Restaurants Certificate of Balcony Inspection

Complete and submit this form if your public lodging establishment is 3 or more stories in height. The inspector must have the education and experience to be competent to perform the inspection. The operator is responsible for verifying the competency of the inspector.

The term "balcony" means "a landing or porch that is accessible to or used by the public..." The balcony inspection must include platforms, stairways, railings and railways, guardrails, balustrades, parapets, and areas enclosed by screening or other non-permanent building material. (Section 509.2112, F.S. and Rule 61C-3.001(5)(a), F.A.C.)

For new or renewal inspections complete sections 1 and 2. For a change of owner attach a copy of previous operator's valid, date-stamped Certificate of Balcony Inspection and complete Section 3.

Owner Name.  Mailing Address  His Richard Jackson Blw  City Anama City Beach  Establishment Name (DBA) Majestic Beach Resort  Establishment Address  10901 Front Beach Road IDBI Front Beach Road  City Panama City Beach  County Bay  Telephone Number(s):  For New or Renewal Only  Section 2 - Inspection  I hereby certify that any and all balconies, platforms, stairways, railings and railways on the above-described premises were inspected on 04/24-28 by a person competent to conduct such inspection, and were found by such person to be safe, secure and free of defects. 08/02 \(\frac{1}{2}\)\(\frac{1}\)\(\frac{1}{2}\)\(\frac{1}{2}\)\(\frac{1}{2}\)\(\frac{1}{2}\)\(\	For New or Renewal Only			
Mailing Address  Mailin	Section 1 – Establishment Information			
State   Zip Code   State   Zip Code   State   Zip Code   State   Zip Code   State	Majestic Beach Resort Dervices LLC	License Number		
Establishment Name (DBA) Majestic Beach Resort  Establishment Address 10901 Front Beach Road  1080 Front Black Rd  City Panama City Beach	Mailing Address 445 Richard Ucclson Blvd			
Establishment Address 10901 Front Beach Road  City Panama City Beach Telephone Number(s):  For New or Renewal Only  Section 2 - Inspection  I hereby certify that any and all balconies, platforms, stairways, railings and railways on the above-described premises were inspected on 0/1/24-20 by a person competent to conduct such inspection, and were found by such person to be safe, secure and free of defects. 08/02 \(\frac{1}{2}\)\(\frac{1}{	Kana and Cara Bock	State	Zip Code 32407	
For New or Renewal Only  Section 2 – Inspection  I hereby certify that any and all balconies, platforms, stairways, railings and railways on the above-described premises were inspected on 01/21-20 by a person competent to conduct such inspection, and were found by such person to be safe, secure and free of defects. 02/02:10/2003  Total Number of Areas Inspected: 523 Total Number of Defects Found: 26 Date Repairs Completed: 08/10/23  The Inspection was conducted by Ben Peters who is competent to conduct such inspections because: (Provide facts/credentials establishing competency on the line below.)  Derek O. Gardner P.E. License #CGC1521883  Signature of Inspector  Date 8-16-23  Name of Operator  Date 8-16-23  For Change of Owner Only  Section 3 – Management Information  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Establishment Name (DBA) Majestic Beach Resort			
For New or Renewal Only  Section 2 – Inspection  I hereby certify that any and all balconies, platforms, stairways, railings and railways on the above-described premises were inspected on 01/21-20 by a person competent to conduct such inspection, and were found by such person to be safe, secure and free of defects. 02/02:10/2003  Total Number of Areas Inspected: 523 Total Number of Defects Found: 26 Date Repairs Completed: 08/10/23  The Inspection was conducted by Ben Peters who is competent to conduct such inspections because: (Provide facts/credentials establishing competency on the line below.)  Derek O. Gardner P.E. License #CGC1521883  Signature of Inspector  Date 8-16-23  Name of Operator  Date 8-16-23  For Change of Owner Only  Section 3 – Management Information  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Establishment Address 10901 Front Beach Road 4 10811 Front Beach Rd			
For New or Renewal Only  Section 2 – Inspection  I hereby certify that any and all balconies, platforms, stainways, railings and railways on the above-described premises were inspected on 04/24-28 by a person competent to conduct such inspection, and were found by such person to be safe, secure and free of defects. 08/02 \(\cdot \) 10/30\(\delta \)  Total Number of Areas Inspected: 523 Total Number of Defects Found: 26 Date Repairs Completed: 08/10/23  The Inspection was conducted by Ben Peters who is competent to conduct such inspections because: (Provide facts/credentials establishing competency on the line below.)  Derek O. Gardner P.E License #CGC1521883  Signature of Inspector  Signature of Operator  Signature of Operator  For Change of Owner Only  Section 3 – Management Information  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new			Zip Code 32407	
Section 2 - Inspection  I hereby certify that any and all balconies, platforms, stairways, railings and railways on the above-described premises were inspected on 04/24-28 by a person competent to conduct such inspection, and were found by such person to be safe, secure and free of defects. 08/02 i 10/2023  Total Number of Areas Inspected: 523 Total Number of Defects Found: 26 Date Repairs Completed: 08/10/23  The Inspection was conducted by Ben Peters who is competent to conduct such inspections because: (Provide facts/credentials establishing competency on the line below.)  Derek O. Gardner P.E. License #CGC1521883  Signature of Inspector  Date 8-16-23  For Change of Owner Only  Section 3 - Management Information  Name of Operator  Management Information  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of the attached previous owner's form. A new				
I hereby certify that any and all balconies, platforms, stairways, railings and railways on the above-described premises were inspected on 01/21-20 by a person competent to conduct such inspection, and were found by such person to be safe, secure and free of defects. 08/02 i/0/2023  Total Number of Areas Inspected: 523 Total Number of Defects Found: 26 Date Repairs Completed: 08/10/23  The Inspection was conducted by Ben Peters who is competent to conduct such inspections because: (Provide facts/credentials establishing competency on the line below.)  Derek O. Gardner P.E License #CGC1521883  Signature of Inspector  Name of Operator  Signature of Operator  Per Change of Owner Only  Section 3 — Management Information  Name of Operator  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new		*		
were inspected on 04/24-28 by a person competent to conduct such inspection, and were found by such person to be safe, secure and free of defects. 08/02 \(\frac{1}{2}\) 0/2023  Total Number of Areas Inspected: 523 Total Number of Defects Found: 26 Date Repairs Completed: 08/10/23  The Inspection was conducted by Ben Peters who is competent to conduct such inspections because: (Provide facts/credentials establishing competency on the line below.)  Derek O. Gardner P.E License #CGC1521883  Signature of Inspector 3 Date 8-16-23  Name of Operator Date 8-16-23  For Change of Owner Only  Section 3 — Management Information  Name of Operator 100 Date 8 1723  Signature of Operator 100 Date 8 1723  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Section 2 – Inspection			
Total Number of Areas Inspected: 523 Total Number of Defects Found: 26 Date Repairs Completed: 08/10/23  The Inspection was conducted by Ben Peters who is competent to conduct such inspections because: (Provide facts/credentials establishing competency on the line below.)  Derek O. Gardner P.E License #CGC1521883  Signature of Inspector Date 8-16-23  Name of Operator Date 8-16-23  For Change of Owner Only  Section 3 - Management Information  Name of Operator Resort Impunity Association for Date 8/1723  Signature of Operator Date 8/1723  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new				
Total Number of Areas Inspected: 523 Total Number of Defects Found: 26 Date Repairs Completed: 08/10/23  The Inspection was conducted by Ben Peters who is competent to conduct such inspections because: (Provide facts/credentials establishing competency on the line below.)  Derek O. Gardner P.E. License #CGC1521883  Signature of Inspector Date 8-16-23  Name of Operator Date 8-16-23  For Change of Owner Only  Section 3 - Management Information  Name of Operator Resort Computing Association for Date 8/1723  Signature of Operator Op				
The Inspection was conducted by Ben Peters who is competent to conduct such inspections because: (Provide facts/credentials establishing competency on the line below.)  Derek O. Gardner P.E. License #CGC1521883  Signature of Inspector  Name of Operator  Signature on Operator  For Change of Owner Only  Section 3 - Management Information  Name of Operator  Name of Operator  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	safe, secure and free of defects. OB/02 : \0 / 2023			
For Change of Owner Only  Section 3 - Management Information  Name of Operator  Signature of Operator  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Total Number of Areas Inspected: 523 Total Number of Defects Found: 26 Date Repairs Completed: 08/10/23			
Derek O. Gardner P.E License #CGC1521883  Signature of Inspector  Name of Operator  Signature of Operator  For Change of Owner Only  Section 3 - Management Information  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	The Inspection was conducted by Ben Peters who is competent to conduct such inspections because: (Provide			
Name of Operator  Signature of Operator  Section 3 - Management Information  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Derek O. Gardner P.E License #CGC1521883			
Name of Operator  Signature of Operator  Section 3 - Management Information  Name of Operator  Name of Operator  Name of Operator  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Signature of Inspector Interest 8-16-23			
Section 3 - Management Information  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Name of Operator		_	
Section 3 - Management Information  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Coastline Engineering & Construction	Inc I	erck Gurdner	
Section 3 – Management Information  Name of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Signature on Operator & -16 - 2:	3		
Name of Operator  Majestic Beach Resort Community Association for B17123  Signature of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new				
Signature of Operator  Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new				
Note: This Certificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Majestic Beach Resort Community Association, Inc. 8117123			
this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Signature of Operator			
this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new	Note: This Cartificate of Balcony Inspection expires three years from the date of inspection listed in Section 2 of			
	this form or from the date of inspection listed in Section 2 of the attached previous owner's form. A new			

STATE OF FLORIDA, DEPARTMENT OF BUSINESS AND PROFESSIONAL REGULATION

Phone: 850.487.1395 - Web: http://www.MyFloridaLicense.com/contactus/ & www.myfloridalicense.com/DBPR/hotels-

restaurants/